

M/s Diamond Cements (Prop. HeidelbergCement India Limited)
Clinkerisation Unit, Narsingarh

Month: Jul 18

TEST REPORT OF FUGITIVE EMISSION MONITORING

| Sl. No. | Locations | Date | SPM ($\mu\text{g}/\text{m}^3$) |
|----------------|--|-------------|--|
| 1 | In between Lime Stone Stock Pile & Coal Yard | 06.07.2018 | 676.33 |
| 2 | Laterite Yard | 06.07.2018 | 896.39 |
| 3 | Near Crusher | 09.07.2018 | 924.14 |
| 4 | Near Raw Mill Silo | 09.07.2018 | 750.87 |
| 5 | Clinker Stock Pile | 10.07.2018 | 1033.22 |
| 6 | Lime Stone Stock Area Line-3 | 10.07.2018 | 945.63 |
| 7 | Coal Stock Area Line-3 | 11.07.2018 | 845.10 |

M/s Diamond Cements (Prop. HeidelbergCement India Limited)

Grinding Unit, Imlai

Month: Jul 18

TEST REPORT OF FUGITIVE EMISSION MONITORING

| Sl. No. | Locations | Date | SPM ($\mu\text{g}/\text{m}^3$) |
|----------------|-------------------------|-------------|--|
| 1 | Clinker Stock Pile | 12.07.2018 | 726.67 |
| 2 | Coal Yard | 12.07.2018 | 866.19 |
| 3 | Gypsum Yard | 13.07.2018 | 748.40 |
| 4 | Fly ash Handling System | 13.07.2018 | 999.36 |
| 5 | Near Cement Silo | 14.07.2018 | 724.94 |

M/s Diamond Cements (Prop. HeidelbergCement India Limited)

Lime Stone Monitoring Mine, Patharia

Month: Jul 18

TEST REPORT OF FUGITIVE EMISSION MONITORING

| Sl. No. | Locations | Date | SPM ($\mu\text{g}/\text{m}^3$) |
|----------------|------------------------------------|-------------|--|
| 1 | Near Loading Point - Belt Conveyor | 19.07.2018 | 835.06 |
| 2 | Haulage Road | 19.07.2018 | 629.12 |
| 3 | Near Crusher | 20.07.2018 | 715.56 |
| 4 | Near Lime Stone Stock Area | 20.07.2018 | 639.00 |
| 5 | Near Drilling Area | 21.07.2018 | 823.48 |