

M/s Diamond Cements (Prop. HeidelbergCement India Limited)
Clinkerisation Unit, Narsingarh

Month: Mar 18

TEST REPORT OF FUGITIVE EMISSION MONITORING

| Sl. No. | Locations | Date | SPM ($\mu\text{g}/\text{m}^3$) |
|----------------|--|-------------|--|
| 1 | In between Lime Stone Stock Pile & Coal Yard | 09.03.2018 | 1458.02 |
| 2 | Laterite Yard | 09.03.2018 | 1237.91 |
| 3 | Near Crusher | 10.03.2018 | 1180.56 |
| 4 | Near Raw Mill Silo | 10.03.2018 | 935.58 |
| 5 | Clinker Stock Pile | 12.03.2018 | 977.73 |
| 6 | Lime Stone Stock Area Line-3 | 12.03.2018 | 1224.11 |
| 7 | Coal Stock Area Line-3 | 13.03.2018 | 1397.52 |

M/s Diamond Cements (Prop. HeidelbergCement India Limited)

Grinding Unit, Imlai

Month: Mar 18

TEST REPORT OF FUGITIVE EMISSION MONITORING

| Sl. No. | Locations | Date | SPM ($\mu\text{g}/\text{m}^3$) |
|----------------|-------------------------|-------------|--|
| 1 | Clinker Stock Pile | 15.03.2018 | 1033.78 |
| 2 | Coal Yard | 15.03.2018 | 983.58 |
| 3 | Gypsum Yard | 16.03.2018 | 1136.51 |
| 4 | Fly ash Handling System | 16.03.2018 | 1466.59 |
| 5 | Near Cement Silo | 17.03.2018 | 1345.76 |

M/s Diamond Cements (Prop. HeidelbergCement India Limited)

Lime Stone Monitoring Mine, Patharia

Month: Mar 18

TEST REPORT OF FUGITIVE EMISSION MONITORING

| Sl. No. | Locations | Date | SPM ($\mu\text{g}/\text{m}^3$) |
|----------------|------------------------------------|-------------|--|
| 1 | Near Loading Point - Belt Conveyor | 22.03.2018 | 951.95 |
| 2 | Haulage Road | 22.03.2018 | 1045.55 |
| 3 | Near Crusher | 23.03.2018 | 1209.00 |
| 4 | Near Lime Stone Stock Area | 23.03.2018 | 998.10 |
| 5 | Near Drilling Area | 24.03.2018 | 1099.68 |